

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Toru OKABAYASHI, et al.

Application No.: 10/057,867

Confirmation No.: 8441

Filed: January 29, 2002

U.S. Patent No.: 6,944,794

Issued: September 13, 2005

For: MICROCONTROLLER WITH DEBUG SUPPORT UNIT



ATTENTION

CERTIFICATE OF CORRECTION

BRANCH

Certificate

MAR 21 2006

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: March 16, 2006

By: H. J. Staas
H. J. Staas
Registration No. 22,010

1201 New York Ave, N.W., 7th Floor
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

MAR 21 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,944,794

DATED : September 13, 2005

INVENTOR(S) : Toru OKABAYASHI, et al.

Title page, (56) References Cited, change "Higashida 714/227" to - - Higashida 712/227 - -.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP
1201 New York Ave., N.W.
7th Floor
Washington, DC 20005

PATENT NO. 6,944,794

No. of add'l copies
@ 50¢ per page

⇒

9.1 2006